## Middlezoy Arts Committee, Footpath Upgrade Work

The Middlezoy Arts group, as part of the 2018 Middlezoy Arts Festival, undertook a major project aimed at improving local footpath access and, in particular the creation of a circular walk with improved access. This project was split into two sections, the first being a series of woodcarving workshops where people were encouraged to carve posts and signs to be installed as part of the upgrade. Tools and tuition were partly funded by the Arts festival.

The second half of the project was the purchase and installation of the materials for upgrade of the footpath furniture. The installation work was undertaken by a group of volunteers.

Major funding for the overall project was provided by Hinkley Point C Community Fund with additional funding and support provided by a number of local companies and individuals.

In all, it is estimated that well over fifty people have been involved with the project in one way or another.

A copy of the circular walk map and some photos of the installations done to date are attached.

We have planned additional work for 2019 to both finish the circular walk and to do additional upgrades aimed at creating a series of "out-and-back" easy access routes. We are also hoping to continue the work in future with further upgrades and clearing of the less used paths.

The wood-carving group has also continued into 2019 with this year's theme being old names. The carvers are working on producing carved wooden signs of the traditional names for streets, lanes and fields around the village.

Middlezoy Heritage Group have provided assistance in deriving traditional names from maps of the village dated 1787 and 1800.

If you would like to get involved are would like further information, please contact:

Ian Henderson
Middlezoy Arts Committee Works Coordinator
ihenderson@live.co.uk

Ph: 077 6601 6603

Woodcarving Group, Funded by Middlezoy Arts Festival 2018



# Footpath upgrade work performed by Middlezoy Arts during 2018

Circular walk map ref 4,







## Circular walk map ref 10



Circular walk map ref 10



Circular walk map ref 11





## Footpath upgrade work planned by Middlezoy Arts for 2019

#### Circular walk map ref B

Existing: Was previously a stile, but presently a temporary metal gate

Proposed: Self-closing gate

Create flat area before and after gate lower than field level. Gate hinged on left, opening into field (towards per photo)

1.0m Oak five bar gate

Self-closing adjustable hinges (Eliza Tinsley)

Trombone style latch

150x150 Oak hinge post, carved

100x100 Oak slam posts

Step to lowered flat gate entry area, reclaimed hardwood railway sleeper

Post and rail to prevent trip/fall hazard to lowered gate entry area

See section 2.6 for details of steps on far side of gate

#### Circular walk map ref A

Existing: Metal kissing gate, poor repair

Proposed: Self-closing gate, hinged on right, opening into field behind (per photo)

1.2m metal gate with forged woodpecker and ivy motif

Self-closing hinges

150x150 Oak hinge post, carved

200x100 Oak slam post (for footpath gate and field gate)

Make good areas previously occupied by kissing gate enclosure (fencing or hedging as

required).

#### Circular walk map ref 8

Existing: Kissing gate, poor repair, broken post

Proposed: Self-closing gate, hinged on left opening into field behind (per photo)

1.2m Metal gate with forged woodpecker and ivy motif

Self-closing hinges

150x150 Oak hinge post, carved 200x100 Oak slam post, carved

Make good areas previously occupied by kissing gate enclosure (fencing or hedging as

required).

## Circular walk map ref B

Existing: Steps, poor repair, several risers missing, no handrail

Proposed: Replace steps with new timber and upright restraints

Install new posts and handrails

